



NUMBER: 23-012-17 REV. A

GROUP: Body

DATE: March 14, 2017

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 23-012-17, DATED MARCH 03, 2017, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDES THE ADDITION OF 2015 AND 2016 MODEL YEARS.**

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 17-021. ALL APPLICABLE UN-SOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE UN-SOLD VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. FOR VEHICLES NOT INCLUDED IN THE RRT VIN LIST, APPLICATION OF THIS SERVICE BULLETIN TO SOLD UNITS IS BASED UPON THE CUSTOMER EXPERIENCING THE SYMPTOM/CONDITIONS. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Wheel Liner Push Pin Fastener Replacement

OVERVIEW:

This bulletin involves replacing both wheel liner push pin fasteners at the front fenders.

MODELS:

****2015 - 2017**** (LD)

Dodge Charger

NOTE: This bulletin applies to vehicles within the following markets/countries: EMEA, NAFTA, LATAM and APAC.

NOTE: This bulletin applies to vehicles built on or before February 02, 2017 (MDH 0202XX).

SYMPTOM/CONDITION:

The customer may describe a rattle from the left, right or both, front wheel openings while driving. This condition is caused from one or both plastic front wheel liner fasteners loosening from their locations.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair.

PARTS REQUIRED:

Qty.	Part No.	Description
2	06506007AA	Rivet

REPAIR PROCEDURE:

1. Turn the steering wheel to full stop one direction at a time and remove both the left and right push fasteners from each wheel liner (Fig. 1). Discard fasteners.

**Fig. 1 Old Fastener**

2. Using a hand plastic rivet tool, install two new rivets on the left and right wheel liners.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
23-02-09-94	Wheel Liner Fastener - Replace (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------