

NUMBER: 31-002-14

GROUP: Collision Bulletin

DATE: September 24, 2014

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS BULLETIN SUPERSEDES TECHNICAL SERVICE BULLETIN 31-002-12, DATED FEBRUARY 02, 2012 WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS AND INCLUDES A CANADIAN PHONE NUMBER.**

SUBJECT:

Safety Certification and Tire Pressure Label Replacement Guidelines

DISCUSSION:

Chrysler has chosen ECS Automotive Concepts to manufacture late model original equipment licensed vehicle information labels for the collision repair industry. Replacement of the Safety Certification label and Tire Pressure label allows a collision repair facility to put a car one step closer to pre-loss condition.





Fig. 1 Tire Label

For more information, visit www.escvin.com or call 1-855-ECSVIN **(U.S. dealers) or 1-636-536-2221 (Canadian dealers)**.

POLICY:

Information Only.